

SLID'UP
by MANTION

INSTRUCTION DE MONTAGE
MONTAGEANLEITUNG
INSTRUCTIONS FOR ASSEMBLY
INSTRUCCIONES DE MONTAJE
INSTRUKCJA MONTAŻU

SLID'UP 110

SU5106
SU5107
SU5108



x1



x2




x2




x2



x2




x1





x2



100
lb




$$d = (L_0 + 2z) / 3$$




t [mm]	5/8, 11/16	3/4, 7/8
y [mm]	0	1/16, 3/16

t [mm]	> 7/8
y [mm]	t - 3/8

1



2



3

