
















$L_{Track} [mm]$	1950	2400	3000
$X [mm]$	840	1120	1400




2



3




4



x4

x8

x4




ø4

ø8,5



x2

4.1



$35 < s < 38$

x4

1


ø4

2


ø8,5

$38 \leq s < 42$


4.2




x8




5








x2




ø6




13



6






x1



x2




ø6





7


x2



#2



7a



7b

