





x1



x2



x4/x5/x6



x2



x2



x1




x2




x2




100
kg






$L_{Track} [mm]$	1950	2400	3000
$X [mm]$	840	1120	1400





SU5950
SU5951






$H_1 = H_0 + 81$
 $H_1 = h + 61$






2






3





4




5






7


x2



#2



7a



7b

