
















$L_{Track} [mm]$	1950	2400	3000
$X [mm]$	840	1120	1400




2



3




4



x4

x8

x4




ø4

ø8,5




x2



4.1

x8




1


ø4

2

ø8,5



4.2




4.3




$35 < s < 38$


$38 \leq s < 42$



x16





5




x2




x2




6





x1



x2




ø6




7


x2



#2



7a



7b

