



SLID'UP
by MANTION

INSTRUCTION DE MONTAGE
MONTAGEANLEITUNG
INSTRUCTIONS FOR ASSEMBLY
INSTRUCCIONES DE MONTAJE
INSTRUKCJA MONTAŻU

SLID'UP 360


SU5750 SU5753
SU5751 SU5754
SU5752 SU5755




x1



x2



x4/x5/x6



x2



x2




x1



x2



x2





x6





x12

120
kg





$L_{Track} [mm]$	1950	2400	3000
$X [mm]$	840	1120	1400





SU5950
SU5951






$$H_1 = H_0 + 81$$

$$H_1 = h + 61$$




2



3



4



L

R


x3

x3




s


4.1



x6



4.2





4.3




$35 < s < 38$


$38 \leq s < 42$




5




x2





x2




L




x2




R



6




x1




x2



ø6



1




2


3

7

x2



#2



7a

7b

